

**TERRA AIR SERVICES**

2950 N. Loop West, Ste 1050
Houston, Texas 77029
Phone (713) 956-6250
FAX (713) 956-2185

FTIR Service Report

North Fenceline

Tosco SFR

1380 San Pablo Avenue
Rodeo, CA 94572-1299

Start		Service	Problem Description	Closed On		
Date	Time	By		Date	Time	Resolution
10/01/1997	10:54:59	na	Lapse	10/01/1997	11:09:55	None
10/09/1997	01:25:31	na	Lapse	10/09/1997	01:45:20	None
10/14/1997	04:49:20	REG	Maintenance	10/14/1997	05:15:16	Work completed - monitor system restarted
10/15/1997	02:11:22	na	Lapse	10/15/1997	02:20:55	None
10/15/1997	05:18:26	na	Weather	10/18/1997	05:38:15	None
10/15/1997	08:57:40	na	Lapse	10/15/1997	09:10:34	None
10/15/1997	09:15:31	na	Lapse	10/15/1997	09:25:21	None
10/16/1997	10:38:52	REG	Maintenance	10/16/1997	11:15:24	Work completed - monitor system restarted
10/16/1997	11:15:24	REG	Maintenance	10/16/1997	11:41:01	Work completed - monitor system restarted
10/18/1997	06:24:16	REG	Maintenance	10/18/1997	10:29:40	Work completed - monitor system restarted
10/23/1997	06:20:52	na	Weather	10/23/1997	07:05:28	None
10/23/1997	07:21:04	na	Weather	10/23/1997	07:45:58	None
10/23/1997	07:45:58	na	Weather	10/23/1997	08:10:48	None
10/23/1997	08:10:48	na	Weather	10/23/1997	08:40:32	None